

		<b>ECCSCM Bean Creek Watershed Spot Sample Monitoring Project - 2014</b>		<b>boldface</b> indicates violation of Michigan Water Standard			
				<b>Water Temp (deg. C)</b>	<b>Dissolved Oxygen mg/L</b>	<b><i>E.coli</i>/100mL</b>	<b>Observations</b>
<b>Date</b>	<b>Site #</b>	<b>Location</b>	<b>Lat/Long</b>				
5/6/14	10	Lime Lake Inlet East, Lime Lk Rd	41° 47' 21.15" N 84° 22' 24.19" W				no flow
5/6/14	9	Lime Lake Inlet, Lime Lk Rd	41° 47' 22.28" N 84° 22' 36.30" W	13	13.9	<10	
6/23/14				18	7.7	370	
5/6/14	11	Tile pipe, Tamarack Rd	41° 47' 48.25" N 84° 23' 7.80" W	13	12.9	50	
6/23/14				17	<b>4.8</b>	100	
5/6/14	14	Medina Drain, Ingall Hwy	41° 48' 10.72"N 84° 17' 34.79"W	13	13.7	170	
6/19/14						<b>&gt;2,419</b>	tested at Adrian Water Treatment Plant
6/23/14				18	6.0	490	
		Unless otherwise noted, <i>E. coli</i> tests from DEQ Lab, Lansing; Dissolved Oxygen results from YSI DO meter.					